

- Palladium Window has been installed.
 - Marvin Windows will replace the center window sash and balance tubes under warranty - Est 6- 8 weeks

- Energy Efficiency
 - Audit results due
 - No update

- Painting
 - Lower level of the rear and side of the church has been painted - thank you Toby.
 - Various paint projects ongoing

- Parsonage Maint.
 - Parsonage shower faucet replaced.
 - Parsonage Dryer timer repaired

- Fire & Safety
 - 90 minute Emergency Light test complete
 - Fire alarm testing complete.
 - Fire Marshal Inspection, addressing findings

- Harrison Hall Carpet Cleaned

- Facility Maintenance Planning updated